

NEW - LCD BUTTON PANELS REPAIR SERVICES						
BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
ARISTOCRAT	LCD BUTTON PANEL	400	ARC	PANELS WITH REFLECTIVE BUTTONS	\$ 450.00	Non touch screen models, some components are proprietary and may not be replaceable, cosmetic damage to face/bezel not repairable.
ARISTOCRAT	LCD BUTTON PANEL	405	HELIX	PANELS WITH REFLECTIVE BUTTONS	\$ 450.00	Non touch screen models, some components are proprietary and may not be replaceable, cosmetic damage to face/bezel not repairable.
ARISTOCRAT	LCD BUTTON PANEL	402	HELIX PLUS	LCD DISPLAY	\$ 690.00	Touch screen model, Touch sensor currently unavailable.
ARISTOCRAT	LCD BUTTON PANEL	401	HELIX	ATI GFA0333600	\$ 450.00	Non touch screen model
ARISTOCRAT	LCD BUTTON PANEL	403	VIRIDIAN	GEN 7	\$ 450.00	Flat rate fee
BALLY/SCI-GAMES	LCD BUTTON PANEL	404	ELITE, AP1, AP2	I-DECK WITH BLACK PANEL	\$ 225.00	Repair excludes replacement of touch sensor, bash button not part of repair or assembly.
BALLY/TWINSTAR	LCD BUTTON PANEL	407	J43	LCD WITH TOUCH PANEL	\$ 225.00	Repair excludes replacement of touch sensor, bash button not part of repair or assembly. Tovis or Effinet.
WMS/SCI-GAMES	LCD BUTTON PANEL	408	BLUEBIRD 2	2.5/3.0 OLED PANEL	\$ 350.00	Includes circuit board replacement, up to two replacements of standard OLED buttons, additional buttons sold separately, large button sold separately, Cosmetic refinishing of bezel face not available.
KONAMI	LCD BUTTON PANEL	406	SELEXION/CONCERTO	LCD PANEL W/ REFLECTIVE BUTTONS	\$ 485.00	Repair does not include cosmetic refinishing of bezel face

TICKET PRINTERS REPAIR SERVICES

BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
JCM FUTURE LOGIC	TICKET PRINTERS	700	RMA REPAIR FUTURE LOGIC PRINTER, GEN 2U, 5	GEN 2U GEN 5	\$ 60.00	Flat fee labor + Print head sold separately
TRANSACT	TICKET PRINTERS	701	RMA REPAIR TRANSACT EPIC 950 PRINTER	Epic 950	\$ 65.00	Flat fee labor + Print head sold separately

Important Info

Customer responsible for shipping & handling costs. It is essential to include all information, including serial numbers to accurately identify each item, understand the problem and determine warrantability. Please use a separate form for each item. You will receive a RMA number and return instructions by the next business day. Please issue PO number repairs and include PO in Details description. Include your email address on your RMA form.

The information and descriptions found in this document is owned and copyrighted by Landry's Holdings, LLC 2019. Contents cannot be utilized, reproduced and/or distributed without the expressed written consent of CasinoTech and Landry Holdings LLC.

LCD / LED MONITORS REPAIR SERVICES						
BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
IGT	LCD / LED MONITOR		6.2" TFT DISPLAY	HITACHI OR KORTEK DISPLAYS SEE PLAYER TRACKING SYSTEM SECTION		
BALLY	LCD / LED MONITOR		6.2" TFT DISPLAY	HITACHI DISPLAY SEE PLAYER TRACKING SYSTEM SECTION		
WMS	LCD / LED MONITOR		6.4"	REFURBISHED UNITS ONLY CONTACT SALES		
LED/LCD DISPLAYS	LCD / LED MONITOR		19" & Under	CAPACITIVE OR P-CAP SENSOR MODELS	\$ 55.00	
LED/LCD DISPLAYS	LCD / LED MONITOR		20"-26"	CAPACITIVE OR P-CAP SENSOR MODELS	\$ 70.00	
LED/LCD DISPLAYS	LCD / LED MONITOR		30"-39"	CAPACITIVE OR P-CAP SENSOR MODELS	\$ 95.00	
LED/LCD DISPLAYS	LCD / LED MONITOR		40"-50"	CAPACITIVE OR P-CAP SENSOR MODELS	\$ 110.00	

CPI BILL VALIDATORS REPAIR SERVICES						
BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
CPI/CRANE	CPI BILL VALIDATORS	500	SC 66 SERIES		\$ 35.00	CASHFLOW HEAD+TRANSPORT MINOR
CPI/CRANE	CPI BILL VALIDATORS	500	SC 66 SERIES		\$ 65.00	CASHFLOW HEAD+TRANSPORT MAJOR
CPI/CRANE	CPI BILL VALIDATORS	501	SCN 66 SERIES		\$ 35.00	ADVANCE HEAD+TRANSPORT MINOR
CPI/CRANE	CPI BILL VALIDATORS	501	SCN 66 SERIES		\$ 65.00	ADVANCE HEAD+TRANSPORT MAJOR
CPI/CRANE	CPI BILL VALIDATORS		EXCHANGE ONLY	Contact Sales		CASHFLOW CASH CAN

CPI CRANE IN WARRANTY REPAIRS: Contact CasinoTech's Sales Representative 702-736-8472 or 346-206-4221
* Minor: Includes cleaning, testing and vanilla firmware. * Major: service rate plus parts.

JCM BILL VALIDATORS REPAIR SERVICES						
BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
JCM	JCM BILL VALIDATORS	503	I-Vizion Head and Transport	Minor repair	\$ 125.00	Flat fee labor + Parts

Important Info

Customer responsible for shipping & handling costs. It is essential to include all information, including serial numbers to accurately identify each item, understand the problem and determine warrantability. Please use a separate form for each item. You will receive a RMA number and return instructions by the next business day. Please issue PO number repairs and include PO in Details description. Include your email address on your RMA form.

The information and descriptions found in this document is owned and copyrighted by Landry's Holdings, LLC 2019. Contents cannot be utilized, reproduced and/or distributed without the expressed written consent of CasinoTech and Landry Holdings LLC.

CPU / MPU - BOARDS + ASSEMBLIES						
BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
AINSWORTH	CPU / MPU - BOARDS + ASSEMBLIES	600	A560		\$ 225.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)

IGT	CPU / MPU - BOARDS + ASSEMBLIES	611	AVP 2.0	75514090W	\$ 200.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	612	AVP 2.5	50061400W	\$ 200.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	616	AVP 3.0M	50062100W	\$ 200.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	614	AVP 625	50062500W, 50062501W	\$ 200.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	615	AVP 660	50062500W, 50062501W	\$ 200.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	617	AVP 3.0 ME	50066000W	\$ 200.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	617	AVP 3.0 ME W/O FAN	50066001W	\$ 200.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	613	AVP 3.0 LC	50067000	\$ 200.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	627	AVP 4.0	50069000	\$ 495.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	632	AVP 4.0 PLUS	50079000	\$ 495.00	Flat fee labor rate (Graphics card and PCI card not included- Sold separately)
IGT	CPU / MPU - BOARDS + ASSEMBLIES	620	S-2000 MPU	75510504	\$ 80.00	Flat fee labor rate
IGT	CPU / MPU - BOARDS + ASSEMBLIES	621	S-2000 ENHANCED MPU	7557270-75512700-755512 - 7557270	\$ 85.00	Flat fee labor rate
IGT	CPU / MPU - BOARDS + ASSEMBLIES	618	GAME KING 3900 / 3902 MPU	75703900, 75703902	\$ 90.00	Flat fee labor rate
IGT	CPU / MPU - BOARDS + ASSEMBLIES	619	GAME KING 044 ENHANCED	75704401-75704402-75704403	\$ 120.00	Flat fee labor rate
WMS	CPU / MPU - BOARDS + ASSEMBLIES	622	BLUE BIRD 1 CPU-NXT	6779-008317-6779-017478	\$ 125.00	Flat fee labor + Graphics Video Card sold separately; Adastra board not available for replacement.
WMS	CPU / MPU - BOARDS + ASSEMBLIES	623	BLUE BIRD 2 CPU-NXT2	A-015455-01-01	\$ 150.00	Flat fee labor + Graphics Video Card sold separately; Adastra board not available for replacement.
WMS	CPU / MPU - BOARDS + ASSEMBLIES	624	BLUE BIRD 2 NXT 3.2	A-026352-03-02	\$ 225.00	Flat fee labor + Graphics Video Card sold separately; Adastra board not available for replacement.
WMS	CPU / MPU - BOARDS + ASSEMBLIES	625	BLUE BIRD 3	Blade	\$ 225.00	Flat fee labor + Graphics Video Card sold separately
WMS	CPU / MPU - BOARDS + ASSEMBLIES	628	BLUE BIRD 2 NXT 3.2X	1445736, 1439750	\$ 475.00	Flat fee labor + Graphics Video Card sold separately
WMS	CPU / MPU - BOARDS + ASSEMBLIES	630	BLUE BIRD 2 NXT 3.5X	1449071	\$ 425.00	Flat fee labor + Graphics Video Card sold separately
SCIENTIFIC GAMES	CPU / MPU - BOARDS + ASSEMBLIES	629	4.2.2X	1453868, 1458980, 1458954, 1454701 i3 GEN4	\$ 475.00	Flat fee labor + Graphics Video Card sold separately
BALLY	CPU / MPU - BOARDS + ASSEMBLIES	605	ALPHA ONE	200173-202080-204965 203588-204694-203604 201819-209194-44603-209195	\$ 175.00	Flat fee labor + Graphics Video Card sold separately
BALLY	CPU / MPU - BOARDS + ASSEMBLIES	606	ALPHA TWO	219737-226458-212233	\$ 275.00	Flat fee labor + Graphics Video Card sold separately
BALLY	CPU / MPU - BOARDS + ASSEMBLIES	607	ALPHA TWO	2.1	\$ 275.00	Flat fee labor + Graphics Video Card sold separately
BALLY	CPU / MPU - BOARDS + ASSEMBLIES	608	ALPHA TWO	2.4	\$ 400.00	Flat fee labor + Graphics Video Card sold separately
BALLY	CPU / MPU - BOARDS + ASSEMBLIES	609	ALPHA TWO	K620	\$ 475.00	Flat fee labor + Graphics Video Card sold separately

Important Info

Customer responsible for shipping & handling costs. It is essential to include all information, including serial numbers to accurately identify each item, understand the problem and determine warrantability. Please use a separate form for each item. You will receive a RMA number and return instructions by the next business day. Please issue PO number repairs and include PO in Details description. Include your email address on your RMA form.

The information and descriptions found in this document is owned and copyrighted by Landry's Holdings, LLC 2019. Contents cannot be utilized, reproduced and/or distributed without the expressed written consent of CasinoTech and Landry Holdings LLC.

CPU / MPU - BOARDS + ASSEMBLIES

BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
KONAMI	CPU / MPU - BOARDS + ASSEMBLIES		K2V	292786	Contact Sales - Replacement might be available (CT ref. 104480)	
KONAMI	CPU / MPU - BOARDS + ASSEMBLIES	626	KP3	310436 SERIES	\$ 350.00	Flat fee labor + Graphics Video Card sold separately
KONAMI	CPU / MPU - BOARDS + ASSEMBLIES	631	KP3.5	310872 SERIES	\$ 350.00	Flat fee labor + Graphics Video Card sold separately
ARISTOCRAT	CPU / MPU - BOARDS + ASSEMBLIES	601	MK6	MK6	\$ 150.00	Flat fee labor + Graphics Video Card sold separately
ARISTOCRAT	CPU / MPU - BOARDS + ASSEMBLIES	602	MK6 XP	MK6 XP	\$ 185.00	Flat fee labor + Graphics Video Card sold separately
ARISTOCRAT	CPU / MPU - BOARDS + ASSEMBLIES	603	MK7	494077A / B REV A / B NON WS	\$ 295.00	Flat fee labor + Graphics Video Card sold separately
ARISTOCRAT	CPU / MPU - BOARDS + ASSEMBLIES	604	MK7	494077-01 / -02, 593104 WS	\$ 295.00	Flat fee labor + Graphics Video Card sold separately
ARISTOCRAT	CPU / MPU - BOARDS + ASSEMBLIES	610	GEN 8 HELIX	494900	\$ 350.00	Flat fee labor + Graphics Video Card sold separately

PLAYER TRACKING SYSTEMS REPAIR SERVICES

BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
BALLY	PLAYER TRACKING SYSTEM	306	6.2" ACSC OR 6.2" SDS	NT Board (ACSC), GMU Board (SDS)	\$ 125.00	Flat fee labor rate
BALLY	PLAYER TRACKING SYSTEM		6.2" ACSC OR 6.2" SDS	Full Replacement (CT ref. 102305)		Significant Damage - Contact Sales Rep for Swap Out, if Available
BALLY	PLAYER TRACKING SYSTEM	300	IVIEW DM DISPLAY MANAGER		\$ 165.00	Flat fee labor rate
BALLY	PLAYER TRACKING SYSTEM	301	IVIEW 2.0 CONTROLLER		\$ 105.00	Flat fee labor rate
BALLY	PLAYER TRACKING SYSTEM	302	IVIEW 3.0 CONTROLLER		\$ 140.00	Flat fee labor rate
IGT	PLAYER TRACKING SYSTEM	304	6.2" LEGACY	70021003	\$ 115.00	Flat fee labor rate
IGT	PLAYER TRACKING SYSTEM	303	6.2" SB1 (NG1)	75441200	\$ 115.00	Flat fee labor rate
IGT	PLAYER TRACKING SYSTEM		6.2" SB2	Contact Sales Representative		Refurbished units may be available (CT ref. 102615)
IGT	PLAYER TRACKING SYSTEM	305	TFT DISPLAY	608009405W, 608050105W	\$ 90.00	Flat fee labor rate
IGT	PLAYER TRACKING SYSTEM		ACRES BE 2 BONUS ENGINE	Contact Sales Representative		Refurbished units may be available (CT ref. 110004)
IGT	PLAYER TRACKING SYSTEM		BE 2 POWER SUPPLY	Contact Sales Representative		Replacement units may be available

Important Info

Customer responsible for shipping & handling costs. It is essential to include all information, including serial numbers to accurately identify each item, understand the problem and determine warrantability. Please use a separate form for each item. You will receive a RMA number and return instructions by the next business day. Please issue PO number repairs and include PO in Details description. Include your email address on your RMA form.

The information and descriptions found in this document is owned and copywritten by Landry's Holdings, LLC 2019. Contents cannot be utilized, reproduced and/or distributed without the expressed written consent of CasinoTech and Landry Holdings LLC.

POWER SUPPLIES REPAIR SERVICES						
BRAND	DEVICE TYPE	CT ref.	PART DESCRIPTION	REF.	SERVICE RATE	Notes
ARISTOCRAT	POWER SUPPLY	805	MK5	PFC 432400, 432947, MK5S2A	\$ 95.00	Flat fee labor rate
ARISTOCRAT	POWER SUPPLY	806	GEN 8	433150	\$ 125.00	Flat fee labor rate
ARISTOCRAT	POWER SUPPLY	807	MK7 - 400 - 1	432666	\$ 125.00	Flat fee labor rate
AINSWORTH	POWER SUPPLY	800	APSM 460	220279	\$ 125.00	Flat fee labor rate
AINSWORTH	POWER SUPPLY	801	SX 750	750 watts	\$ 125.00	Flat fee labor rate
KONAMI	POWER SUPPLY	816	K2V	400 watts	\$ 120.00	Flat fee labor rate
KONAMI	POWER SUPPLY	817	190825 A		\$ 125.00	Flat fee labor rate
KONAMI	POWER SUPPLY	818	KP3	400 watts	\$ 125.00	Flat fee labor rate
KONAMI	POWER SUPPLY	819	TDK LAMBDA	VA-26936, COSEL SKON9021	\$ 125.00	Flat fee labor rate
ARUZE	POWER SUPPLY	812	DELTA EDPS-350DB	GEN X E131881	\$ 160.00	Flat fee labor rate
ARUZE	POWER SUPPLY	813	DELTA ADP555-AR	CUBE X APX	\$ 150.00	Flat fee labor rate
ARUZE	POWER SUPPLY	814	DELTA EDPS-560DB	560 watt	\$ 125.00	Flat fee labor rate
ARUZE	POWER SUPPLY	815	DELTA EDPS-750AB	750 watt	\$ 125.00	Flat fee labor rate
BALLY	POWER SUPPLY	810	SHENZHEN CP172001 / TMG 720B	ALPHA 212385	\$ 125.00	Flat fee labor rate
BALLY	POWER SUPPLY	N/A	AS 4238-065	S6000	Contact Sales - Offer Replacement	
BALLY	POWER SUPPLY	811	DZ300 SERIES	DZ300-1EUFV1, 2EUFV3, 12EU 201101, 201102, 209768 YH2351, YH1361 300 watt	\$ 90.00	Flat fee labor rate
IGT	POWER SUPPLY	809	WINTACT, EURASIA, 3Y	TMG-Z 369, CP-9826, CP-8018 MCP-8011, TMG-Z361B 40009000, 1, 2, 3, 90 WP203F11 300 watt models	\$ 90.00	Flat fee labor rate
IGT	POWER SUPPLY		3Y	YM-7451A, CP-1037 40010101 440 watt	Contact Sales - Offer Replacement	
IGT	POWER SUPPLY	808	WINTACT, EURASIA, 3Y	CP-8442, CP-8443, YM-2441A WP210F11, WP206F11 440 watt	\$ 90.00	Flat fee labor rate
IGT	POWER SUPPLY		WINTACT, EURASIA, 3Y	40019001—9002—9003—4000 CP-8444 440 watt	Contact Sales - Offer Replacement	
IGT	POWER SUPPLY		EURASIA	40013000	Contact Sales - Offer Replacement (CT ref. 107508 -107509)	
IGT	POWER SUPPLY		3.0 CPU	75831000 / WP 306D11	Contact Sales - Offer Replacement	
IGT	POWER SUPPLY		AVP 2.5, AVP 3.0	75831001 / WP 306D11	Contact Sales - Offer Replacement	
WMS	POWER SUPPLY	802	BB2 ARP-9016-05	850 watts	\$ 125.00	Flat fee labor rate
WMS	POWER SUPPLY		BB1 ARP-2501-00	Contact Sales - Offer Replacement		
WMS	POWER SUPPLY	803	BB2	UNI 750 / Setec, 018547, 6765-0020716-01-00	\$ 125.00	Flat fee labor rate
WMS	POWER SUPPLY		BB1	ARAS EVP-3005	Contact Sales - Offer Replacement (CT. ref 107557)	
WMS	POWER SUPPLY		BB1 SECONDARY POWER SUPPLY	A015310-01-00	Contact Sales - Offer Replacement (CT. ref 107558)	

Important Info

Customer responsible for shipping & handling costs. It is essential to include all information, including serial numbers to accurately identify each item, understand the problem and determine warrantability. Please use a separate form for each item. You will receive a RMA number and return instructions by the next business day. Please issue PO number repairs and include PO in Details description. Include your email address on your RMA form.

The information and descriptions found in this document is owned and copyrighted by Landry's Holdings, LLC 2019. Contents cannot be utilized, reproduced and/or distributed without the expressed written consent of CasinoTech and Landry Holdings LLC.